

**NATIONAL  
SENIOR CERTIFICATE**

**GRADE 12**

**SEPTEMBER 2019**

**MECHANICAL TECHNOLOGY:  
WELDING AND METALWORK  
MARKING GUIDELINE**

**MARKS: 200**

---

This marking guideline consists of 18 pages.

---

**QUESTION 1: MULTIPLE-CHOICE QUESTIONS (GENERIC)**

- 1.1 C ✓ (1)
- 1.2 A ✓ (1)
- 1.3 B ✓ (1)
- 1.4 D ✓ (1)
- 1.5 A ✓ (1)
- 1.6 C ✓ (1)
- [6]**

**QUESTION 2: SAFETY (GENERIC)**

- 2.1 **Reasons for wearing a helmet:**  
Protects your eyes from ultra violet rays and infra-red rays. ✓✓ (2)
- 2.2 **Angle grinder safety:**
- Safety guard must be in place before grinding. ✓
  - Protective shields must be placed around the object being ground to protect passers-by. ✓
  - Use the correct grinding disc for the job.
  - Do not use excessive force while grinding and cutting.
  - Make sure there are no cracks on the disc before you start a job.
  - Protective clothing and eye protection are essential. (Any 2) (2)
- 2.3 **Maximum gap – bench grinder:**  
3 mm ✓ (1)
- 2.4 **Band saw safety:**
- Wear safety glasses or a face shield. ✓
  - Wear protective footwear when required. ✓
  - Make sure all guards are in place. ✓
  - Check for correct tension on the blade.
  - Use blades that are sharp, properly set and suitable for the job.
  - Keep the floor clean and free of obstructions or clutter. (Any 3) (3)
- 2.5 **Gas cylinder safety precautions:**
- Always store and use gas cylinders in an upright position. ✓
  - Never stack cylinders on top of one another. ✓
  - Do not bang or work on the cylinders.
  - Never allow cylinders to fall.
  - No oil and grease should come into contact with gas cylinders or fittings.
  - Keep the caps on the cylinders for protection. (Any 2) (2)

**[10]**

**QUESTION 3: MATERIALS (GENERIC)****3.1 Quenching:**

- Quenching means to cool the heated material rapidly. ✓
- Cooling the material to room temperature. ✓
- Water is normally used for low and medium carbon steels. ✓
- Oil is used on high carbon and alloy steel.
- Extreme cooling brine is used.

(Any 3) (3)

**3.2 Difference between brine and salt water:**

- Brine hardens steels better than fresh water, salt inhibits the water from dissolving into atmospheric gas. ✓
- Salt water does not vaporise as quickly as fresh water. ✓

(2)

**3.3 Purpose for case-hardening:**

- It hardens the surface. ✓
- It provides a wear resistant surface. ✓
- Strengthens core to withstand applied loads. ✓

(3)

**3.4 Methods of case-hardening:**

- Mild steel can be surface hardened by heating to its critical range and immersing in case hardening compound. Carbon is absorbed into surface layer of steel. ✓✓
- Mild steel can be heated in an atmosphere of nitrogen called Nitriding. ✓✓

(Any 1 x 2) (2)

**3.5 Difference between *annealing* and *normalising*:**

Annealing requires steel to cool down over an extended period thus resulting in an internal structural change in the steel, making it softer. ✓✓  
Normalising merely removes work-related stresses. ✓✓

(4)

**[14]**


**QUESTION 4: MULTIPLE-CHOICE QUESTIONS (SPECIFIC)**

- |      |     |             |
|------|-----|-------------|
| 4.1  | C ✓ | (1)         |
| 4.2  | D ✓ | (1)         |
| 4.3  | A ✓ | (1)         |
| 4.4  | B ✓ | (1)         |
| 4.5  | A ✓ | (1)         |
| 4.6  | C ✓ | (1)         |
| 4.7  | A ✓ | (1)         |
| 4.8  | B ✓ | (1)         |
| 4.9  | C ✓ | (1)         |
| 4.10 | C ✓ | (1)         |
| 4.11 | A ✓ | (1)         |
| 4.12 | B ✓ | (1)         |
| 4.13 | A ✓ | (1)         |
| 4.14 | C ✓ | (1)         |
|      |     | <b>[14]</b> |


**QUESTION 5: TERMINOLOGY (TEMPLATES) (SPECIFIC)****5.1 Roof truss:**

- A – Purlins ✓
- B – Internal bracing member/s ✓
- C – Ridging ✓
- D – Roof covering ✓
- E – Rafter ✓

(5)

**5.2 Fillet weld on T-joint:**

(7)

**5.3 Dimensions of the material:**

Average  $\varnothing$  = inside  $\varnothing$  + sheet thickness ✓

Average  $\varnothing$  = 476 mm + 12 mm

Average  $\varnothing$  = 488 ✓

Average perimeter =  $\pi \times$  Average  $\varnothing$

Average perimeter =  $(\pi \times 488 \text{ mm}) \div 2$

Average perimeter = 766,54 mm ✓

Total length needed = 766,54 + 60 mm + 60 mm ✓

Total length needed = 886,55 mm ✓

Round off to 887 mm ✓

(6)

- 5.4
- Flange templates ✓
  - Web templates ✓
  - Strip templates ✓

(3)

- 5.5
- Hand saws ✓
  - Chisels ✓
  - Plane
  - Cordless drill and drill bits
  - Steel tap
  - Straight edge
  - Compass, trammels
  - Squares
  - Protractors
  - Chalk lines etc.

(Any 2) (2)  
[23]


**QUESTION 6: TOOLS AND EQUIPMENT (SPECIFIC)**

- 6.1 **Danger of oil – Oxy-Acetylene:**  
It can catch alight. ✓ (1)
- 6.2 **Uses of a bench grinder:**  
• To sharpen cutting tools and drill bits. ✓  
• To remove rough edges. ✓  
• To remove excess material. ✓ (3)
- 6.3 6.3.1 **Spot welding equipment:**  
Uses the heating effect, ✓ which occurs when a current flows through a resistance, ✓ to fuse two plates together. ✓ (3)
- 6.3.2 **Punch and shearing machine:**  
Are being used for cutting steel profiles ✓✓ and punching holes into steel plates. ✓✓ (4)
- 6.4 **Types of rolling machines:**  
• Horizontal pyramid rolls ✓  
• Off-set pinch rolls ✓  
• Vertical rolls ✓ (3)
- 6.5 • Centre screw used to adjust the die. ✓  
• Two side screws used to secure the die. ✓ (2)
- 6.6 **Consequences of soft material-bench grinder:**  
The soft material lodges in the pores of the wheel and expands. ✓  
Pieces can dislodge when the wheel is revolving at high speed causing injury. ✓ (2)

**[18]**

## QUESTION 7: FORCES (SPECIFIC)

7.1




MEMBER	STRUT	TIE	FORCE	
AE	✓		15,3 N	✓
BG	✓		11,3 N	✓
CH	✓		12,2 N	✓
FG	✓		6,9 N	✓
EF				
DE		✓	13,25 N	✓
DF		✓	13,25 N	✓
DH		✓	6,2 N	✓
GH		✓	7 N	✓

(20)



## 7.2



## 7.2.1 Reactions at the supports RL and RR

**Moments about RR**

$$RL \times 12 = (5 \times 9) + (6 \times 6) + (4 \times 3) \checkmark$$

$$RL \times 12 = 45 + 36 + 12$$

$$RL = \frac{93}{12} \checkmark$$

$$RL = 7,75 \text{ N} \checkmark$$

**Reactions about RL**

$$RR \times 12 = (4 \times 9) + (6 \times 6) + (5 \times 3) \checkmark$$

$$RR \times 12 = 36 + 36 + 15$$

$$RR = \frac{87}{12} \checkmark$$

$$RR = 7,25 \text{ Kn} \checkmark$$

(6)

7.2.2 **Shear forces:**

$$SF_A = 0 \text{ Kn} \checkmark$$

$$SF_B = 7,75 - 5$$

$$= 2,75 \text{ Kn} \checkmark$$

$$SF_C = 7,75 - 5 - 6$$

$$= -3,25 \text{ Kn} \checkmark$$

$$SF_D = 7,75 - 5 - 6 - 4$$

$$= -7,25 \text{ Kn} \checkmark$$

$$SF_E = 7,75 - 5 - 6 - 4 + 7,75$$

$$= 0 \text{ kN} \checkmark$$

(5)

7.2.3 **Bending moments:**

$$BM_A = 0 \text{ kN.m} \quad \checkmark$$


$$\begin{aligned} BM_B &= (7,75 \times 3) \\ &= 23,25 \text{ kN.m} \quad \checkmark \end{aligned}$$

$$\begin{aligned} BM_C &= (7,75 \times 6) - (5 \times 3) \\ &= 46,5 - 15 \\ &= 31,5 \text{ kN.m} \quad \checkmark \end{aligned}$$


$$\begin{aligned} BM_D &= (7,75 \times 9) - (5 \times 6) - (6 \times 3) \\ &= 69,75 - 30 - 18 \\ &= 21,75 \text{ kN.m} \quad \checkmark \end{aligned}$$

$$\begin{aligned} BM_E &= (7,75 \times 12) - (5 \times 9) - (6 \times 6) - (4 \times 3) \\ &= 93 - 45 - 36 - 12 \\ &= 0 \text{ kN.m} \quad \checkmark \end{aligned}$$

(5)

7.2.4 **Shear force diagram:**

## 7.2.5 Bending moment diagram:

(5)  
[45]

**QUESTION 8: JOINING METHODS (INSPECTION OF WELD) (SPECIFIC)****8.1 Welding spatter:**

It is molten material that are generated at or near the welding arc. ✓

Causes: Disturbance in the molten weld pool during the transfer of wire into the weld. ✓

- Voltage too low ✓
- Amperage too high ✓

(4)

**8.2 Liquid dye test:**

- Clean the surface to be inspected and spray the liquid dye to penetrate into the surface. ✓
- Allow liquid dye to penetrate. ✓
- Remove excess dye with cleaner. ✓
- Spray a developer onto the surface to bring out the colour. ✓
- Areas where the dye has penetrated (defects) will show up clearly. ✓

(5)

**8.3 8.3.1 Undercutting:**

- Improper settings of equipment ✓
- Welding speed too fast ✓
- Current too high

(Any 2)

(2)

**8.3.2 Slag inclusion:**

- Incorrect current settings ✓
- Included angle too narrow ✓
- Rapid chilling
- Previous weld slag has not been removed

(Any 2)

(2)

**8.3.3 Porosity:**

- Atmospheric contamination ✓
- Surface contamination ✓
- Dirty or wet electrodes when arc welding
- Rusted MIG wire

(Any 2)

(2)

**8.3.4 Lack of fusion:**

- Poor welding technique ✓
- Travel speed is too slow ✓
- Using a very wide weld joint
- Weld current too low

(Any 2)

(2)

- 8.4**
- Correct flame for the work on hand ✓
  - Correct angle of blowpipe and rod ✓
  - Depth of fusion and amount of penetration ✓
  - Rate of progress along the joint

(Any 3)

(3)

**8.5 Types of cracks:**

- Heat affected zone cracks. ✓
- Centreline cracks. ✓
- Crater cracks. ✓
- Transverse cracks. ✓

(2)

**8.6 Nick-break test:**

It tests for internal welding defects. ✓

(1)

**[23]**

**QUESTION 9: JOINING METHODS (STRESSES AND DISTORTION)  
(SPECIFIC)**

- 9.1 Weld distortion is the warping of the base plate ✓ caused by heat from the welding arc / flame. ✓ (2)
- 9.2 **Distortion and residual stress:**
- Heat present in the weld. ✓
  - Qualities of parent metal, filler rod or electrode. ✓
  - Shape and size of weld. ✓
  - Number of successive welds runs.
  - Comparative weight of weld metal and parent metal.
  - Type of welding joint used. (Any 3) (3)
- 9.3 **Reduce distortion:**
- Do not over weld. ✓
  - Intermittent welding. ✓
  - Place welds near the neutral axis. ✓
  - Use as few passes as possible.
  - Use back step welding.
  - Anticipate the shrinkage forces.
  - Planning the welding sequence.
  - Using strong backs.
  - Using clamps, jigs and fixtures. (Any 3) (3)
- 9.4 **Steel groups:**
- Low carbon steel: ✓ 0,15 – 0,30% carbon. ✓
  - Medium carbon steel: ✓ 0,31 – 0,70% carbon. ✓
  - High carbon steel: ✓ 0,71 – 1,5 % carbon. ✓ (6)
- 9.5 **Difference between cold working and hot working of steel:**  
Cold working is when deformation of steel takes place below ✓ the recrystallisation temperature ✓ of the steel.  
Hot working is when deformation of steel takes place above ✓ the recrystallisation temperature ✓ of the steel. (4)

**[18]**

**QUESTION 10: MAINTENANCE (SPECIFIC)**

- 10.1 **Locking out of large machines before maintenance:**
- Due to the danger associated with large machines ✓
  - To ensure that isolation switches are switched off ✓
  - To ensure that switches are locked out and tagged to inform others that maintenance work is being done
  - To ensure that nobody can turn the machine on while maintenance is being done (Any 2 x 1) (2)
- 10.2 **Tagging plates:**
- It has multiple holes so that more than one technician can lock out the machine simultaneously. ✓ (1)
- 10.3 **Major and minor services for power-driven guillotine:**
- Major** service allows for on-going service procedures that are designed to maintain the guillotines in premium working conditions. ✓
- Minor** service is designed to minimise major mechanical and electrical failures, by employing the principle of preventative maintenance. ✓ (2)
- 10.4 **Maintenance guidelines for a pedestal drilling machine:**
- Visual checks of electrical wiring, switches, etc. ✓
  - Verify that all guards are secure and function correctly. ✓
  - Ensure workspace is clear.
  - Confirm availability and conditions of PPE.
  - Lubricate moving parts.
  - Use moisture-penetrating oil spray to prevent rust.
  - Check for availability of specific tools.
  - Check the run-out of the spindle.
  - Inspect belts for wear.
  - Ensure the drive belt is correctly tensioned.
  - Check the condition of the rack and pinion mechanisms and lubricate.
  - Ensure cuttings are removed.
  - Inspect the Morse taper sleeves for burrs/scratches.
  - Check the security of machine mountings. (Any 2) (2)
- 10.5 **Overloading a punch and shearing machine:**
- Dulling or breaking blades/punches. ✓
  - Putting strain on the motor and drive mechanism. (Any 1) (1)
- [8]

**QUESTION 11: TERMINOLOGY (DEVELOPMENT) (SPECIFIC)****11.1 Conical hopper:****11.1.1 Vertical height (DE):**

$$\tan \theta = \frac{\text{opposite}}{\text{adjacent}} \quad \checkmark$$

$$\begin{aligned} DE &= \tan 70^\circ \times EC \\ &= 2,75 \times 1 \\ &= 2,75 \text{ m} \quad \checkmark \end{aligned}$$

(2)

**11.1.2 Main radius (AC):**

$$\cos \theta = \frac{\text{adjacent}}{\text{hypotenuse}}$$

$$\begin{aligned} AC &= \frac{BC}{\cos 70^\circ} \quad \checkmark \\ &= \frac{2}{0,34} \end{aligned}$$

$$= 5,88 \text{ m} \quad \checkmark$$

(2)

**11.1.3 Small radius (AD):**

$$\cos \theta = \frac{\text{adjacent}}{\text{hypotenuse}}$$

$$\begin{aligned} DC &= \frac{EC}{\cos 70^\circ} \quad \checkmark \\ &= \frac{1}{0,34} \end{aligned}$$

$$= 2,94 \text{ m} \quad \checkmark$$

Now AD can be calculated.

$$AD = AC - DC$$

$$= 5,88 - 2,94$$

$$= 2,94 \text{ m} \quad \checkmark$$

(3)

**11.1.4 Circumference:**

$$\begin{aligned} \text{Circumference:} &= \pi \times GD \\ &= \pi \times 4 \quad \checkmark \\ &= 12,57 \text{ m} \quad \checkmark \end{aligned}$$

(2)



## 11.2 Square-to-round transition piece:

### 11.2.1 The true length FG is firstly needed to draw the pattern:

$$IK = 300 \text{ (2 units)}$$

$$IH = 150 \text{ (1 units)}$$

$$HK = 1\sqrt{3} \text{ (1 unit} \times \sqrt{3} \text{)}$$

The true length FG:

$$\begin{aligned} \text{Plan length FG} &= FG - GK \quad \checkmark \\ &= 400 - 300 \\ &= 100 \text{ mm} \quad \checkmark \end{aligned}$$

The true length FG is equal to H'F

$$\begin{aligned} H'F^2 &= H'G^2 + GF^2 \quad \checkmark \\ &= 800^2 + 100^2 \\ H'F &= \sqrt{650\,000} \quad \checkmark \end{aligned}$$

$$\text{True length FG} = 806 \text{ mm} \quad \checkmark \quad (5)$$

### 11.2.2 To determine the plan length CI, the sides CE and EI of triangle CEI must be calculated.

$$CE = CF - EF$$

$$= 400 - 150$$

$$= 250 \text{ mm} \quad \checkmark$$

But EI = FH

$$FH = FK - HK$$

$$= 400 - 259,8$$

$$= 140,2 \text{ mm} \quad \checkmark$$

$$\text{True Length (CI)} = FH^2 + EI^2 \quad \checkmark$$

$$= 250^2 + 140,2^2$$

$$= \sqrt{82156,04}$$

$$= 286,63 \text{ mm} \quad \checkmark \quad (4)$$

11.2.3 **JI is one-twelfth of the circumference**

$$\text{Circumference} = \pi \times \text{GD}$$

$$= \pi \times 600$$

$$= 1\,884,9 \text{ mm} \quad \checkmark$$

$$\frac{1}{12} \text{ Circumference} = \frac{1884,9}{12} \quad \checkmark$$

$$= 157,1 \text{ mm} \quad \checkmark$$

(3)

**[21]****TOTAL: 200**