

**NATIONAL
SENIOR CERTIFICATE**

GRADE 12

SEPTEMBER 2019

**MECHANICAL TECHNOLOGY:
FITTING AND MACHINING
MARKING GUIDELINE**

MARKS: 200

This marking guideline consists of 16 pages.

QUESTION 1: MULTIPLE-CHOICE QUESTIONS (GENERIC)

- 1.1 C ✓ (1)
- 1.2 A ✓ (1)
- 1.3 B ✓ (1)
- 1.4 D ✓ (1)
- 1.5 A ✓ (1)
- 1.6 C ✓ (1)
- [6]**

QUESTION 2: SAFETY (GENERIC)

- 2.1 **Reason for wearing a helmet:**
Protects your eyes from ultra violet rays and infra-red rays. ✓✓ (2)
- 2.2 **Angle grinder safety:**
- Safety guard must be in place before grinding. ✓
 - Protective shields must be placed around the object being ground to protect passers-by. ✓
 - Use the correct grinding disc for the job.
 - Do not use excessive force while grinding and cutting.
 - Make sure there are no excessive force while grinding and cutting.
 - Make sure there are no cracks on the disc before you start a job.
 - Protective clothing and eye protection are essential. (Any 2) (2)
- 2.3 **Maximum gap – bench grinder:**
3 mm ✓ (1)
- 2.4 **Band saw safety:**
- Wear safety glasses or a face shield. ✓
 - Wear protective footwear when required. ✓
 - Make sure all guards are in place. ✓
 - Check for correct tension on the blade.
 - Use blades that are sharp, properly set and suitable for the job.
 - Keep the floor clean and free of obstructions or clutter. (Any 3) (3)
- 2.5 **Gas cylinder safety precautions:**
- Always store and use gas cylinders in an upright position. ✓
 - Never stack cylinders on top of one another. ✓
 - Do not bang or work on the cylinders.
 - Never allow cylinders to fall.
 - No oil and grease should come into contact with gas cylinders or fittings.
 - Keep the caps on the cylinders for protection. (Any 2) (2)
- [10]**

QUESTION 3: MATERIALS (GENERIC)**3.1 Quenching:**

- Quenching means to cool the heated material rapidly. ✓
- Cooling the material to room temperature. ✓
- Water is normally used for low and medium carbon steels. ✓
- Oil is used on high carbon and alloy steel.
- Extreme cooling brine is used.

(Any 3) (3)

3.2 Difference between brine and salt water:

- Brine hardens steels better than fresh water, salt inhibits the water from dissolving into atmospheric gas. ✓
- Salt water does not vaporise as quickly as fresh water. ✓

(2)

3.3 Purpose for case-hardening:

- It hardens the surface. ✓
- It provides a wear resistant surface. ✓
- Strengthens core to withstand applied loads. ✓

(3)

3.4 Methods of case-hardening:

- Mild steel can be surface hardened by heating to its critical range and immersing in case hardening compound. Carbon is absorbed into surface layer of steel. ✓✓
- Mild steel can be heated in an atmosphere of nitrogen called Nitriding. ✓✓

(Any 1 x 2) (2)

3.5 Difference between *annealing* and *normalising*:

Annealing requires steel to cool down over an extended period thus resulting in an internal structural change in the steel, making it softer. ✓✓
Normalising merely removes work-related stresses. ✓✓

(4)

[14]

QUESTION 4: MULTIPLE-CHOICE QUESTIONS (SPECIFIC)

- | | | |
|------|-----|-----|
| 4.1 | B ✓ | (1) |
| 4.2 | D ✓ | (1) |
| 4.3 | C ✓ | (1) |
| 4.4 | A ✓ | (1) |
| 4.5 | D ✓ | (1) |
| 4.6 | B ✓ | (1) |
| 4.7 | D ✓ | (1) |
| 4.8 | B ✓ | (1) |
| 4.9 | B ✓ | (1) |
| 4.10 | A ✓ | (1) |
| 4.11 | D ✓ | (1) |
| 4.12 | B ✓ | (1) |
| 4.13 | D ✓ | (1) |
| 4.14 | B ✓ | (1) |

[14]

QUESTION 5: TERMINOLOGY (LATHE AND MILLING MACHINE) (SPECIFIC)**5.1 Lathe components:**

5.1.1 Lead screw transmits feed motion for screw-cutting and extends the length of the bed, passing behind the apron. ✓✓ (2)

5.1.2 Tailstock stocks supports the free end of work and is also in drilling, reaming and taper turning operations of work held in the chuck or on the faceplate. ✓✓ (2)

5.1.3 Lathe steadies is used to support long pieces of small-diameter must be machined in a centre lathe. To prevent them from bending additional support on the free end. ✓✓ (2)

5.2 Diving head: Is a supplementary component used to break up the circumference of a circular workpiece into a number of equal parts. ✓ (1)

5.3 Taper-turning calculations:

$$\Theta = 8,5^\circ$$

$$\theta/2 = 4,25^\circ \checkmark$$

$$\tan \theta/2 = (D - d) / 2L \checkmark$$

$$\tan 4,25 \times 2 \times 250 = (55-d) \checkmark \checkmark$$

$$d = 17,84 \text{ mm}$$

$$d = 18 \text{ mm} \checkmark \quad (5)$$

5.4 Keyway cut:

A – Side and face cutter ✓

B – Engineers Square ✓

C – Key way ✓

D – Work piece ✓

(4)

5.5 Lead Calculations:


$$\text{Lead} = \text{No. of starts} \times \text{pitch}$$

$$= 3 \times 2,5 \text{ mm} \checkmark$$

$$= 7,5 \text{ mm} \checkmark$$


(2)

[18]

QUESTION 6: TERMINOLOGY (INDEXING) (SPECIFIC)**6.1 GEAR CALCULATIONS:****6.1.1 Down Cutting**


✓✓

(2)

6.1.2 Up-cutting

✓✓

(2)

6.1.3 Straddle milling

✓✓

(2)

6.2 Advantages of tailstock set-over method:

Long and accurate tapers can be cut. ✓

(1)

6.3 Module is the ratio of pitch diameter to the number of the teeth, generally regarded as tooth size. ✓

(1)

6.4 Gear ration of dividing is 40 : 1 meaning 40 revolutions of the worm shaft to one turn of the worm gear. ✓✓

(2)

6.5 Differential indexing

<i>Hole circles</i>											
<i>Side 1</i>	24	25	28	30	34	37	38	39	41	42	43
<i>Side 2</i>	46	47	49	51	53	54	57	58	59	62	66

<i>Standard change gears</i>										
24 x 2	28	32	40	44	48	56	64	72	86	100

6.5.1 Simple indexing

$$\text{Indexing} = \frac{40}{N} = \frac{40}{119}$$

$$\begin{aligned} \text{Actual indexing} &= \frac{40}{A} \\ &= \frac{40}{120} = \frac{4 \times 2}{12 \times 2} \\ &= \frac{8}{24} \end{aligned}$$

Zero full turns and 8 holes on the 24 - hole circle ✓✓✓

(3)

6.5.2 Change of gears

$$\frac{D_r}{D_n} = \frac{A - N}{A} \times \frac{40}{1} \quad \checkmark$$

$$\frac{D_r}{D_n} = \frac{120 - 119}{120} \times \frac{40}{1} \quad \checkmark$$

$$\frac{D_r}{D_n} = \frac{1}{120} \times \frac{40}{1} \quad \checkmark$$

$$\frac{D_r}{D_n} = \frac{40}{120} = \frac{4}{12} \times \frac{6}{6} \quad \checkmark$$

$$\frac{D_r}{D_n} = \frac{24}{72} \quad \checkmark\checkmark$$

(5)

6.5.3 The direction of motion is clockwise.

The crank handle will turn the same direction as index plate. ✓

(1)

6.6 Dove tail calculations:

Dovetail calculations

$$R = \frac{D}{2} = 10 \text{ mm} \quad \checkmark$$

$$\alpha = \frac{\theta}{2}$$

$$\tan \alpha = \frac{R}{a}$$

$$W = 229 \text{ mm}$$

$$X = 300 \text{ mm}$$

$$300 = 2a + 2R + 229 \quad \checkmark$$

$$300 = (2 \times a) + (2 \times 10) + 229 \quad \checkmark$$

$$a = 25,5 \text{ mm} \quad \checkmark$$

$$\alpha = 21,41^\circ \quad \checkmark$$

$$\theta = 2 \times \alpha \quad \checkmark$$

$$\theta = 42,825^\circ \quad \checkmark$$

(7)

6.7 Reference Systems:

- Absolute Measurements \checkmark
- Incremental measurements \checkmark

(2)

[28]

QUESTION 7: TOOLS AND EQUIPMENT (SPECIFIC)**7.1 Testers:**

7.1.1 Tensile tester is a destructive tester that subjects a piece of material to an increasing axial load while measuring the corresponding elongation of the material. ✓✓ (2)

7.1.2 Moments testers is used to determine the reactions on either side of a simply loaded beam and illustrate the concept of the triangle of forces. ✓✓ (2)

7.2 Depth gauge:

- open container
- pipe or cylinders (2)

7.3 Screw thread micrometres


$6 + 0,5 + 0,3 = 6,80 \text{ mm}$ ✓✓ (2)

7.4 Setting up the Brinell Hardness tester:

- The desired load in kilograms is selected on the dial by adjusting the air regulator.
- The specimen is placed on the anvil.
- The specimen is raised to be in contact with the Brinell ball by turning the hand wheel.
- The load is then applied by pulling out the plunger control.
- Remove the specimen from the tester and measure the diameter of the impression.
- Determine the Brinell hardness number by calculation or by using the table.

✓✓✓✓✓ (5)

[13]

QUESTION 8: FORCES (SPECIFIC)**8.1 Resultant Force Calculations:****FIGURE 8.1**

$$X_{com} = 100 \cos 30 + 150 \cos 60 - 125 \cos 60 - 75 \cos 45 \quad \checkmark \checkmark$$

$$= 152,135 \text{ N} \quad \checkmark$$

$$Y_{com} = 100 \sin 30 + 75 \sin 45 - 125 \sin 60 - 150 \sin 60 \quad \checkmark \checkmark$$

$$= 124,683 \text{ N} \quad \checkmark$$

$$R = \sqrt{X^2 + Y^2} \quad \checkmark$$

$$R = 196,7 \text{ N} \quad \checkmark$$

$$\tan \theta = y/x \quad \checkmark$$


$$\theta = 124,683/152,135 \quad \checkmark$$

$$\theta = 39,336^\circ \quad \checkmark$$

Equilibrant = Resultant BUT IN THE OPPOSITE DIRECTION ✓

$$\text{Equilibrant} = 196,7 \text{ N at } 219,336^\circ \quad \checkmark \checkmark \quad (13)$$

8.2 Moments:



Converting the UDL to Point Load

$$5 \times 10 = 50 \text{ kN @ 5m} \quad \checkmark$$

Calculation of the Reactions Taking moments:

$$R_2 \times 10 = (30 \times 3) + (50 \times 5) + (20 \times 7) \quad \checkmark$$

$$= 48 \text{ kN} \quad \checkmark$$

$$R_1 \times 10 = (20 \times 3) + (50 \times 5) + (30 \times 7) \quad \checkmark$$

$$= 52 \text{ kN} \quad \checkmark$$

(5)

8.3 Stress Calculations

8.3.1 Tensile stress calculations

$$F = 12 \text{ kN}; \delta = 24,5 \text{ MPa}; L = 250 \text{ mm}; E = 90 \text{ PGa}$$

$$A = \frac{F}{\delta}$$

$$= 12 \times 10^3 / 24,5 \times 10^6 \quad \checkmark$$

$$A = 4,898 \times 10^{-4} \text{ m}^2 \quad \checkmark$$

$$A = \pi r^2$$

$$d = \sqrt{4A/\pi} \quad \checkmark$$

$$d = 0,02494 \text{ m} \quad \checkmark$$

$$d = 24,97 \text{ mm} \approx 25 \text{ mm} \quad \checkmark$$

(5)

8.3.2 The change in length calculations

$$\Delta L = ?; E = 90 \text{ GPa}; F = 12 \text{ Kn}; L = 250 \text{ mm}; \delta = 24,5 \text{ MPa}$$

$$\Delta L = \frac{S \times L}{E} \quad \checkmark$$

$$= (24,5 \times 10^6 \times 0,25) / 90 \times 10^9 \quad \checkmark \checkmark$$

$$= \underline{0,0681 \text{ mm}} \quad \checkmark \checkmark$$

(5)

8.4 Stress/Strain diagram:

A – Limit of Proportionality \checkmark

B – Elastic limit \checkmark

C – Yield point \checkmark

D – Maximum Force/Point \checkmark

E – Point of Fracture \checkmark

(5)

[33]

QUESTION 9: MAINTENANCE (SPECIFIC)**9.1 Basic preventative maintenance:**

9.1.1 PVC – Polyvinyl chloride ✓ (1)

9.1.2 GRP – Glass Fibre Reinforced ✓ (1)

9.1.3 LDPE – Polyethylene Low Density ✓ (1)

9.2 Reasons for using cutting fluid when working on the centre lathe:

- It prolongs the life of a cutting tool. ✓
- It prevents the shavings or metal chips from sticking and fusing to the cutting tool. ✓
- It will carry away the heat generated by the turning process.
- It flushes away shavings/metal chips. ✓
- It improves the quality of the finish of the turned surface. (Any 1) (1)

9.3 Factors that influence the coefficient of friction:

- Contact pressure ✓
- Surface roughness ✓
- Temperature ✓
- Sliding velocity ✓
- Type of lubrication ✓ (Any 3 x 1) (3)

9.4 Reasons for using carbon fibre:

- It light in weight ✓
- It is tougher and stronger ✓
- It can be bent to any shape when heated above 150 °C. (Any TWO) (2)

9.5 ONE property and ONE use of each composites:

	Composite	Property	Uses	
9.5.1	Vesconite	<ul style="list-style-type: none"> - wear resistance - very versatile - high load bearing strength - high chemical resistance - Very low co-efficient of friction (Any 1) 	<ul style="list-style-type: none"> - Discs - Thrust washers - Wear pads - Vanes - Light duty gears (Any 1) 	(2)
9.5.2	Teflon	<ul style="list-style-type: none"> - Withstands high temperatures - self-lubrication - resistant to water, grease heat and corrosion. (Any 1) 	<ul style="list-style-type: none"> - Orthopaedic and prosthetic appliances. - Hearing aid - upholstery (Any 1) 	(2)
9.5.3	Nylon	<ul style="list-style-type: none"> - toughness, hard-wearing, cheap, needs little maintenance (1) 	<ul style="list-style-type: none"> - Bushes - gears - Pulleys (1) 	(2)

9.6 Consequences for failure to do maintenance:

- Risk of injury or death (e.g. Failed brakes) ✓
- Financial loss due to damage suffered as a result of part failure ✓
- Loss of valuable production time. ✓

(3)


[18]

QUESTION 10: JOINING METHODS (SPECIFIC)**10.1 Square Thread Calculations:**

$$\begin{aligned}
 10.1.1 \quad \text{Helix (Tan } \theta) &= \frac{\text{Lead}}{\pi D} && \checkmark \\
 &= 45 / (\pi \times 84) && \checkmark \\
 \text{Tan } \theta &= 0,17 && \checkmark \\
 \Theta &= 9,677^\circ && \checkmark
 \end{aligned}
 \tag{4}$$

$$\begin{aligned}
 10.1.2 \quad \text{Leading Tool Angle} &= 90 - (\text{Helix} + \text{Clearance}) && \checkmark \\
 &= 90 - (9,677 - 3.) && \checkmark \\
 &= 77,323^\circ && \checkmark
 \end{aligned}
 \tag{3}$$

$$\begin{aligned}
 10.1.3 \quad \text{Trailing/Following tool angle} &= 90 + (\text{Helix} - \text{Clearance}) && \checkmark \\
 &= 90 + (9,677 - 3) && \checkmark \\
 &= 96,677^\circ && \checkmark
 \end{aligned}
 \tag{3}$$

10.2 Screw thread diagram:

(6)

10.3 Units Conversion:

$$\begin{aligned}
 &40,125^\circ \\
 &40,125 - 40 = 0,125 \\
 &0,125 \times 60 = 7,5 \checkmark \\
 &40^\circ 7'30'' \checkmark
 \end{aligned}$$

(2)

[18]

QUESTION 11: SYSTEMS AND CONTROL (DRIVE SYSTEMS) (SPECIFIC)

- 11.1 Gear drives work on the principle that the turning motion of one gear be transferred to another gear if the gears are mounted close so that they mesh or engage. ✓✓ (2)

11.2 **Hydraulic system:**11.2.1 **Calculate the Force applied on Piston A.**

$$d_a = 28 \text{ mm}; D_b = 148 \text{ mm}; X_a = 80 \text{ mm}; X_b = ?$$

$$P = \frac{F}{A}$$

$$A = \pi D_a^2 / 4 \quad \checkmark$$

$$= \pi (0,028)^2 / 4 \quad \checkmark$$

$$= \underline{6,158 \times 10^{-4} \text{ m}^2} \quad \checkmark$$

$$F = P \times A$$

$$= 0,4 \times 10^6 \times 6,158 \times 10^{-4} \quad \checkmark$$

$$\text{Force} = 246,3 \text{ N} \quad \checkmark$$

(5)

11.2.2 **Volume displaced in the system:**

$$\text{Vol}@_a = \text{Vol}@_b \quad \checkmark$$

$$A_a \times S_{La} = A_b \times S_{Lb} \quad \checkmark$$

$$\pi D_a^2 / 4 \times 80 = \pi D_b^2 / 4 S_{Lb} \quad \checkmark \checkmark$$

$$S_{LB} = 2,86 \text{ mm} \quad \checkmark \checkmark$$

(6)

11.3 **Functions of a reservoir in a hydraulic system:**

- A fluid storage tank
- Promotes air separation from the fluid.
- Supports for the pump and electric motor
- Promotes heat dispersion
- Acts as a base plate for mounting control equipment ✓✓ (Any 2 x 1) (2)

11.4 **Belt drive calculations:**

$$N_{\text{motor}} \times D_{\text{motor}} = N_{\text{blade}} \times D_{\text{blade}} \quad \checkmark$$

$$125 \times 1100 = 375 \times D_{\text{blade}} \quad \checkmark$$

$$D_{\text{blade}} = 366,667 \text{ rpm} \quad \checkmark$$

(3)

11.5 **Belt drive advantages:**

- They produce less noise and vibrations
- They do not require parallel shafts
- They are simple and cheaper to install compare to other drives
- They do not need lubrication
- Belt drives are very efficient. ✓✓

(2)

11.6 **Compound Gear calculations:**

$$11.6.1 \quad \frac{N_{output}}{N_{motor}} = \frac{T_{i24} \times T_{i20} \times T_{i42}}{T_{v40} \times T_{v48} \times T_{v90}} \checkmark$$

$$N = \frac{24 \times 20 \times 42}{40 \times 48 \times 90} \times 1440 \quad \checkmark \checkmark$$

$$N_{output} = 168 \text{ rpm} \quad \checkmark \quad (4)$$

$$11.6.2 \quad VR = \frac{N_{driver}}{N_{final}} \quad \checkmark$$

$$VR = 1440/168 \quad \checkmark$$

$$VR = 60 : 7 \quad \checkmark \quad (3)$$

11.7 **Derivation of Units:**

$$\begin{aligned} \text{Torque} &= \text{Force (F)} \times \text{Radius (r)} \\ &= (\text{N}) \times (\text{m}) \\ &= \text{N.m} \quad \checkmark \end{aligned}$$

(1)

[28]**TOTAL: 200**