



Province of the
EASTERN CAPE
EDUCATION

**NATIONAL
SENIOR CERTIFICATE**

GRADE 11

NOVEMBER 2016

**MECHANICAL TECHNOLOGY
MEMORANDUM**

MARKS: 200

This memorandum consists of 13 pages.

QUESTION 1: MULTIPLE-CHOICE QUESTIONS

1.1	C ✓	(1)
1.2	C ✓	(1)
1.3	B ✓	(1)
1.4	A ✓	(1)
1.5	C ✓	(1)
1.6	B ✓	(1)
1.7	D ✓	(1)
1.8	C ✓	(1)
1.9	D ✓	(1)
1.10	D ✓	(1)
1.11	D ✓	(1)
1.12	C ✓	(1)
1.13	C ✓	(1)
1.14	D ✓	(1)
1.15	D ✓	(1)
1.16	D ✓	(1)
1.17	D ✓	(1)
1.18	C ✓	(1)
1.19	B ✓	(1)
1.20	A ✓	(1)
		[20]

QUESTION 2: SAFETY

- 2.1
- Store full cylinders apart from empty ones. ✓
 - Keep cylinders in a cool place. ✓
 - Always store and use cylinders in an upright position. ✓
 - Never stack cylinders on top of one another. ✓
 - Do not bang or work on cylinders. ✓
 - Cylinders must be chained to prevent them from falling. ✓
 - Do not allow oil or grease to come into contact with oxygen fittings as oil and oxygen together are flammable. ✓ (Any 3 x 1) (3)
- 2.2
- Guards must be fitted correctly. ✓
 - Ensure there is no oil or grease in front of the machine or the floor. ✓
 - Check that the tool rest is no more than 3 mm from the wheel. ✓
 - Step aside when starting the machine. ✓
 - Dress uneven wheels with an emery wheel dresser. ✓
 - Grind only on the face of the grinding wheel and never on the side. ✓
 - Never force grinding so as to slow the machine down. ✓ (Any 2 x 1) (2)
- 2.3
- Wear personal protective clothing. ✓
 - Wear correctly shaded welding helmet. ✓
 - Wear rubber soled shoes. ✓
 - Ensure that equipment and cables are in good condition. ✓
 - Floors must be dry. ✓
 - There should be adequate ventilation to remove harmful fumes. ✓
 - All electrodes must be kept dry. ✓ (Any 3 x 1) (3)
- 2.4
- All guards must be in place. ✓
 - No loose clothing. ✓
 - No oil or grease on the floor in front of the machine. ✓
 - Do not use hands to remove cuttings. ✓
 - Never adjust the cutting tool while machine is running.
 - Do not lean as a habit on the machine.
 - Do not attempt to stop the chuck by placing your hand on the chuck while the machine is slowing down. (Any 2 x 1) (2)

[10]**QUESTION 3: TOOLS AND EQUIPMENT**

- 3.1
- Horizontal milling machine ✓
Vertical milling machine ✓ (2 x 1) (2)
- 3.2
- Clean the tool after using it. ✓
Store it safely after using it. ✓
Ensure that the sockets fit properly onto it. ✓ (Any 2 x 1) (2)

- 3.3
- Taper taps ✓
 - Second or intermediate taps ✓
 - Bottoming taps or plug taps ✓
- (3)
- 3.4
- Clean after use. ✓
 - Never force the drill. ✓
 - Oil the machine regularly. ✓
 - Check rack on side of pillar column for damage. ✓
 - Release the table lock before adjusting. ✓
- (Any 3 x 1) (3)
- 3.5 Oxygen ✓ and
Acetylene ✓
- (2)
[12]

QUESTION 4: MATERIALS

- 4.1 Changing the structure and grain of metals ✓ by applying heat. ✓
- (2)
- 4.2
- Low carbon steel ✓
 - Medium carbon steel ✓
 - High carbon steel ✓
- (Any 2 x 1) (2)
- 4.3
- Water ✓
 - Oil ✓
 - Brine
 - Liquid salts
 - Molten lead
 - Soluble oil
 - Air
- (Any 2 x 1) (2)
- 4.4
- 4.4.1 C ✓
- (1)
- 4.4.2 B ✓
- (1)
- 4.4.3 D ✓
- (1)
- 4.4.4 A ✓
- (1)
- 4.5
- Heating the metal slowly to a certain temperature to ensure a uniform temperature. ✓
 - Soaking the metal. ✓
 - Cooling the metal at a certain rate to room temperature. ✓
- (3)
[13]

QUESTION 5: TERMINOLOGY5.1 Arbor cutters:

- Plain milling ✓
- Side milling ✓
- Staggered tooth
- Slitting

(Any 2 x 1) (2)

Shank cutters

- End mills ✓
- Shell-end ✓
- T-slot
- Woodruff

(Any 2 x 1) (2)

5.2 Divides the circumference of the work piece into any number of equal parts. ✓
 Holds the work piece in the required position while cuts are being made. ✓

(2)

5.3 5.3.1 The surface may be produced by any manufacturing process. ✓ (1)

5.3.2 It indicates the amount of stock to be removed. ✓ (1)

- 5.4
- Rapid indexing ✓
 - Simple indexing ✓

(2)

5.5 NOTE: $\frac{\theta}{2} = \frac{6^\circ}{2} = 3^\circ$ ✓

$$\tan \theta = \frac{D-d}{2 \times L} \quad \checkmark$$

$$\tan 3^\circ = \frac{50-d}{2 \times 120} \quad \checkmark$$

$$0,0524 = \frac{50-d}{240} \quad \checkmark$$

$$d = 0,0524 \times 240 - 50 \quad \checkmark$$

$$d = 37,42 \text{ mm} \quad \checkmark$$

(6)

$$5.6 \quad \sin \theta = \frac{\text{Distance across the flat side (X)}}{40}$$

$$X = \sin \theta \times 40$$

$$X = \sin 60^\circ \times 40 \quad \checkmark$$

$$X = 0,866 \times 40 \quad \checkmark$$

$$X = 34,64 \text{ mm} \quad \checkmark \text{ (Distance across the flat side)}$$

$$\text{Depth of cut (x)} = \frac{40 - X}{2} \quad \checkmark$$

$$x = \frac{40 - 34,64}{2} \quad \checkmark$$

$$x = 2,68 \text{ mm} \quad \checkmark \text{ (Depth of cut of the biggest hexagon)} \quad (6)$$

$$5.7 \quad \text{Indexing} = \frac{40}{N} \quad \checkmark$$

$$= \frac{40}{20} \quad \checkmark$$

$$\text{Indexing} = 2 \text{ Full turns} \quad \checkmark \quad (3)$$

$$5.8 \quad 5.8.1 \quad \text{Force} \quad \checkmark \quad (1)$$

$$5.8.2 \quad \text{Pa.} \quad \checkmark \quad (1)$$

$$5.8.3 \quad \text{Watt} \quad \checkmark \quad (1)$$

5.9 Bow's notation:

It is the method which can be used to simplify problem solving \checkmark where three or more forces are applied to a body in a system of forces. \checkmark (2)

[30]

QUESTION 6: JOINING METHODS

6.1 6.1.1 Square butt joint:



(2)

6.1.2 Double-V-butt joint:



(2)

6.1.3 Single-J-butt joint:



(2)

6.2 Welding positions:

- Flat position. ✓
- Horizontal position. ✓
- Vertical position. ✓
- Oblique position. ✓
- Overhead position
- All round position

(Any 4 x 1) (4)

6.3 Rightward gas welding:

- Rightward gas welding or backhand gas welding is usually used for welding material 4 mm thick and thicker. ✓
- Here the rod follows the flame, ✓ which tends to anneal the welded joint as the welding progresses. ✓
- The rod is held at 30° – 40° with the base metal and the flame at 40° – 50°. ✓

(4)

6.4 Shut down procedure:

- Shut off the acetylene and oxygen stop valves. ✓
- Shut off the gas mains.(cylinder valves) ✓
- Purge the system. ✓
- Reset regulators to zero outlet pressure. ✓
- Close the torch valves. ✓

(5)

6.5 Welding symbol elements:

- Reference line ✓
- Arrow ✓
- Weld symbol ✓
- Supplementary symbol(s) ✓
- Dimension(s) ✓
- Tail ✓
- Specification, process or other reference(s)

(Any 6 x 1) (6)
[25]

QUESTION 7: FORCES7.1 Resultant:

If a system of forces acts on a body and a single force can be found ✓
that has the same effect as the system, that single force is known as
the resultant. ✓

(2)

7.2 Types of forces:

- Resultant ✓
- Equilibrium ✓
- Equilibrant ✓

(3)

7.3 Given:

Load = 12 kN = 12×10^3 N
Stress = ?

$$\begin{aligned} \text{Cross sectional area} &= \frac{\pi D^2}{4} \\ &= \frac{\pi 25^2}{4} \checkmark \\ &= \frac{\pi \cdot 625}{4} \checkmark \\ &= 490,9 \text{ mm}^2 \checkmark \end{aligned}$$

$$\begin{aligned} \text{Stress} &= \frac{12 \times 10^3}{4,909 \times 10^{-4}} \checkmark \\ &= 24\,444\,897 \text{ Pa} \checkmark \end{aligned}$$

$$\text{Stress} = 24,445 \text{ MPa} \checkmark \quad (6)$$

$$7.4 \quad \text{Stress} = \frac{\text{Load}}{\text{Cross sectional area}}$$

$$= \frac{10 \times 10^3}{400} \checkmark \checkmark$$

$$= \frac{10 \times 10^3}{\frac{400}{10^6}} \checkmark \checkmark$$

$$= 25\,000\,000 \text{ Pa} \checkmark$$

$$= 25 \text{ MPa} \checkmark \quad (6)$$

$$\begin{aligned} 7.5 \quad 7.5.1 \quad RL: (RR \times 8) &= (4 \times 3) + (5 \times 5) \checkmark \\ &= 12 + 25 \checkmark \\ &= 37 \checkmark \\ RR &= 4,625 \text{ N} \checkmark \end{aligned} \quad (4)$$

AND

$$\begin{aligned} RR: (RL \times 8) &= (5 \times 3) + (4 \times 5) \checkmark \\ &= 15 + 20 \checkmark \\ &= 35 \checkmark \\ RL &= 4,375 \text{ N} \checkmark \end{aligned} \quad (4)$$

7.5.2 Bending moments:

$$\begin{aligned} BM_A &= (4,375 \times 3) \checkmark = 13,125 \text{ N} \checkmark \\ BM_B &= (4,375 \times 5) - (4 \times 2) \checkmark \\ &= 21,875 - 8 \checkmark \\ &= 13,875 \text{ N} \checkmark \end{aligned} \quad (5)$$

[30]

QUESTION 8: MAINTENANCE

- 8.1 Reasons for doing wheel alignment.
- To ensure maximum tyre life. ✓
 - Optimal road holding. ✓
 - To reduce excessive tyre wear.
 - To reduce steering or tracking problems. (Any 2 x 1) (2)
- 8.2 Implications of unbalanced revolving parts:
- Causes excessive wear. ✓
 - Causes vibration. ✓ (2)
- 8.3
- Types of balancing:
 - Static balancing ✓
 - Dynamic balancing. ✓ (2)
- 8.4 8.4.1 Fluid friction:
Objects moving through liquid or gas experience fluid friction or drag. ✓✓ (2)
- 8.4.2 Rolling friction:
Rolling friction works against the motion of a rolling object e.g. a cricket ball on the outfield of a cricket ground as it moves away from the batsman. ✓✓ (2)
- 8.4.3 Sliding friction:
Sliding friction is the force that resists the motion ✓ of an object as it moves along a surface. ✓ (2)
- 8.5 Ackerman principle
- To avoid having the tyres slip sideways when cornering. ✓
 - To reduce tyre wear. ✓ (2)
- 8.6 Meaning of calamities:
Disasters. ✓ (1)

[15]

QUESTION 9: SYSTEMS AND CONTROL9.1 Factors of grip of belt drives:

- The area of contact ✓
 - The tension ✓
 - The coefficient of friction ✓
- (3)

9.2 Advantages of belt drives:

- It is cheaper than gear drives. ✓
 - It is quieter than gear drives. ✓
- (2)

9.3 Disadvantages of gear drives:

- A great deal of wear and tear is caused by friction. ✓
 - Gears are difficult and expensive to manufacture. ✓
 - Large amounts of power are needed to overcome friction between them.
- (2)

9.4 Function of valves in hydraulic system:

- Regulating pressure in a circuit. ✓
 - Directing hydraulic fluid into a specific direction. ✓
 - Determine the amount of fluid that will flow in the circuit.
- (2)

9.5 Speed of the driven shaft:

$$\pi \times D_A \times N_A = \pi \times D_B \times N_B$$

$$\pi \times 250 \times 700 = \pi \times 120 \times N_B \quad \checkmark$$

$$N_B = \frac{\pi \times 250 \times 700}{\pi \times 120} \quad \checkmark \checkmark$$

$$N_B = 1\,458,3 \text{ rpm} \quad \checkmark$$

(4)

9.6 Pressure in hydraulic fluid:

$$\text{Area} = \frac{\pi D^2}{4}$$

$$A = \frac{\pi 320^2}{4}$$

$$A = 80\,424 \text{ mm}^2 \quad \checkmark$$

$$\text{Pressure} = \frac{F}{A} \quad \checkmark$$

$$P = \frac{15\,000}{80\,424} \quad \checkmark$$

$$P = 187,5 \text{ kPa} \quad \checkmark$$

(5)

9.7 Calculation of output speed:

$$\frac{N_O}{N_T} = \frac{T_A \times T_C}{T_B \times T_D}$$

$$\frac{N_O}{840} = \frac{35 \times 43}{86 \times 70} \checkmark$$

$$\frac{N_O}{840} = \frac{1\ 505}{6\ 020}$$

$$N_O = 0,25 \times 840 \checkmark$$

Output speed = 210 rpm \checkmark (3)

9.8 Applications of screw threads:

- To hold parts together. \checkmark
- To transmit motion. \checkmark
- To transmit power. \checkmark
- To adjust parts with reference to one another. \checkmark

(4)
[25]

QUESTION 10: PUMPS

10.1 Parts of reciprocating pumps:

- Inlet valve. / Intake valve. / Admission valve (Any 1) \checkmark
- Outlet valve. / Discharge valve. / Exhaust valve (Any 1) \checkmark
- Plunger / Piston. (Any 1) \checkmark

(3)

10.2 Advantages of gear pumps:

- Very efficient. \checkmark
- Can develop high pressure. \checkmark
- No reciprocating parts that can cause vibration. \checkmark
- Drive is always positive.
- No valves or springs.

(Any 3 x 1) (3)

10.3 Disadvantages of vane pump:

- Wear on the vanes are high. \checkmark
- The pump cannot develop high pressure. \checkmark
- They can cause pulsation. \checkmark

(3)

10.4 Causes of "water hammer"

- The valve or stop cock in the pipeline can suddenly close. \checkmark
- During the delivery stroke, the water moves up the delivery pipe. \checkmark

(2)

10.5 Definition of "water hammer"

- Water hammer is a loud hammering in the pipeline, which is called the "knock" sound. $\checkmark\checkmark$

(2)

10.6 Causes of pump slip:

- Worn external packing. ✓
- Worn internal packing. ✓
- A strainer exposed above the fluid level. ✓
- A faulty foot valve. ✓
- Faulty or loose flanges or joints. ✓
- A weak or faulty seat or spring of a valve.

(Any 5 x 1) (5)

10.7 Types of relief valves:

- A plunger pressure relieve valve. ✓
- A ball pressure relieve valve. ✓

(2)
[20]**TOTAL: 200**