

VRAESTEL 1 VRAAG 1  
GR 11 NOVEMBER 2010


PAPER 1 QUESTION 1  
GR 11 NOVEMBER 2010

Question 1(a) / Vraag 1(a)

QUESTIONS		ANSWERS	
1	Identify two deliberate drawing errors in the bathroom.	1. WC faces the wrong way. 2. Wash basin is in doorway.	2
2	Identify one deliberate drawing error in the bedroom.	Incorrect door representation.	1
3	Identify one deliberate drawing error in the garage.	Outside wall too thin	1
4	Identify three deliberate drawing errors in the south elevation.	1. NFL Should be NGL. 2. Door placed incorrectly. 3. Left window opening incorrect.	3
5	What is the floor finish in the garage?	Grano	1
6	What does BIC stand for?	Built-in cupboards	1
7	What is the floor area of the lounge?	9,916 m <sup>2</sup>	2
9	What is the perimeter of the house?	29,314 m	3
10	What view will be seen in the direction of arrow A?	West view	1
<b>TOTAL</b>			<b>15</b>

VRAE		ANTWOORDE	
1	Identifiseer twee opsetlike tekenfoute in die badkamer.	1. WC omgekeer. 2. Wasbak is in pad van deur.	2
2	Identifiseer een opsetlike tekenfout in die slaapkamer.	Inkorrekte deurvoorstelling.	1
3	Identifiseer een opsetlike tekenfout in die motorhuis.	Buitemuur te dun	1
4	Identifiseer drie opsetlike tekenfoute in die suidaansig.	1. NVV moet NGV wees. 2. Deur in verkeerde posisie. 3. Linker vensteropening in verkeerde posisie.	3
5	Wat is die vloerafwerking in die motorhuis?	Grano	1
6	Wat staan IGK voor?	Ingeboude kaste	1
7	Bepaal die vloerarea van die sitkamer.	9,916 m <sup>2</sup>	2
9	Bepaal die omtrek van die huis.	29,314 m	3
10	Watter aansig sal in die rigting van pyl A gesien word?	Wesaansig	1
<b>TOTAAL</b>			<b>15</b>

Question 1(b) / Vraag 1(b)



[ 5 ]

MEMORANDUM

2